

## Tools you need.

- ①Iron (30W)
- ②Solder wire
- ③Multimeter
- ④Tweezers
- ⑤Wire cutters

## Precautions:

- ①Check part values & quantities against part list
- ②Always meter resistor values before soldering
- ③Understand all part polarities and orientations

## HV-1 High voltage lighter kit instructions

Rev. 1.0

July 25, 2017

Produced by YiQi

**1. Front machining:**

- ① Bend the pin of the transformer 90 degrees. Pay attention to the direction of the bending
- ② From the transformer shell where 5mm cut excess copper wire
- ③ Use a knife to gently scrape off the paint about 5mm of the enameled wire

**2. Processing triode**  
Bend the triode as 90 degrees (Note the polarity direction)

**3. Install diode:**  
Install 1N4007 to D1

**4. Install resistance.**  
Install 33R/1W to R1

HV-1 Electronic ignitor component list

NO.	Name	Mode	QTY
R1	R. E. S	33R/1W	1
C1	E. Cap	470UF	1
D1	Diode	1N4007	1
SW1	Contact switch	6*6*5	1
Q1	Triode	D880	1
JK1	Battery terminal	KF301-2P	1
T1	Transformer	14*15*8	1
—	PCB	HV-1 (18*71mm)	1
Q1	Screw	M3*5	1
Q1	Screw cap	M3	1
T1	Binding band	3*100mm	1

**5. Install transistor to Q1**  
Be careful not to weld now

**6. Fix the triode on the PCB**  
with a screw  
The back is locked with a nut

**7. Finally, weld the triode.**

**8. Install starting switch:**  
Contact switch to SW1

**9. Bend the electrolytic capacitor to 90 degrees**  
Note the polarity direction

**10. Install the battery terminals to JK1**

**11. ①Install the transformer to the T1**  
Be careful not to weld now.  
**②Secure the transformer to the PCB with a harness**  
Then weld. Notice that the direction of the transformer cannot be reversed

**12. Check the integrity of the component welds**  
To connect the power  
Notice : The use of direct current 3-5V3A  
Two of the translucent top of the line bending distance is about 5mm

